

Quality is Behind the Diamond[®]

SAFETY DATA SHEET

Section 1. PRODUCT AND COMPANY IDENTIFICATION

Product Name: Other Identifiers: Recommended Use: Manufacturer: Internet Address: Address:

Company Telephone: E-mail Address: Emergency Contacts: Argon Argon Charging agent in fire extinguishers. AMEREX CORPORATION <u>www.amerex-fire.com</u> 7595 Gadsden Highway, P.O. Box 81 Trussville, AL 35173-0081 (205) 655-3271 customer.service@amerex-fire.com Chemtrec 1(800) 424-9300 or (703) 527–3887 February 9th, 2021

Revised:

Section 2. HAZARDS IDENTIFICATION

GHS – Classification

Health	Environmental	Physical
Acute Toxicity: Category None	None	None
Skin Corrosion/Irritation: None	None	None
Skin Sensitization: NO	None	None
Eye: Category None	None	None
STOT – None	None	None
Carcinogen: Category None	None	None

Gas Under Pressure

GHS – Label Symbol(s):

 \diamond

GHS – Words(s):

Other Hazards Not Resulting in Classification:

Warning

Argon is a simple asphyxiate. May displace oxygen and cause rapid suffocation.

May cause frostbite in contact with skin or eyes.

Page 1 of 10 Pages <u>Argon</u> <u>SDS Part Number 26929</u>

GHS Hazard	GHS Codes(s)	Code Phrase(s)
Physical	H280	*- Contains gas under pressure; may explode if heated.
	281	Contains refrigerated gas; may cause cryogenic burns or injury.
Health	H313	May be harmful in contact with skin.
	332	Harmful if inhaled.
Environmental	None	
Precautionary:		
General	P101	If medical advice is needed, have product container or label at hand
Prevention	251	Do not pierce of burn, even after use.
	261	Avoid breathing gas.
	271	Use only outdoors or in a well-ventilated area.
	280	Wear protective gloves/protective clothing/eye protection/face protection. [As modified by IV
		ATP].
	282	Wear cold insulating gloves/face shield/eye protection
Response	P312	Call a POISON CENTER/ doctor//if you feel unwell. [As modified by IV ATP]
	321	Specific treatment (see Section 4 – First Aid Measures).
	336	Thaw frosted parts with lukewarm water. Do not rub affected areas.
	304+340	IF INHALED: Remove person to fresh air and keep comfortable for breathing.
	305+310	IF IN EYES: Immediately call a doctor.
	313+333	May be harmful in contact with skin or if inhaled.
Storage	P405	Store locked up
	403+233	Store in a well ventilated place. Keep container tightly closed
	410+403	*- Protect from sunlight. Store in well-ventilated place.
Disposal	P501	Dispose of contents through a licensed disposal company. Contaminated container should be disposed of as unused product.

GHS – Hazard Phrases

*- If under pressure

Section 3. COMPOSITION/INFORMATION ON INGREDIENTS

Chemical Name	EC No.	REACH Reg. No.	CAS-No.	Weight %	Classification
Argon	231-147-0		7440-37-1	100	NA

Colorless, odorless.

Emergency overview:

Adverse health effects and symptoms:

None in normal quantities. Simple aphyxiant and can cause frostbite on skin and in eyes.

Section 4. FIRST AID MEASURES

Eye Exposure:

Can cause freezing injury to eyes. Flush eyes with cool water for 15 minutes; hold eyelids open during the irrigation to assure that all surfaces are flushed. Seek medical attention immediately.

Page 2 of 10 Pages <u>Argon</u> SDS Part Number 26929

Skin Exposure:	May cause cold burns or frostbite. Remove contaminated clothing and flush affected areas with lukewarm (NOT HOT) water. Seek medical attention immediately if blistering of the dermal surface or if deep tissue freezing occurs.
Inhalation:	May cause irritation, along with coughing. If respiratory irritation or distress occurs remove victim to fresh air. Seek medical attention if irritation persists.
Ingestion:	Argon is a simple asphyxiate. May cause coughing, dizziness, headache, dyspnea, unconsciousness and death. If symptoms appear or respiratory distress occurs, remove victim to fresh air. Seek medical attention immediately.
Medical conditions possibly	, , , , , , , , , , , , , , , , , , ,
aggravated by exposure:	None

Section 5. FIRE-FIGHTING MEASURES

Flammable Properties: Flash Point: Suitable Extinguishing Media:	Not flammable None Non-combustible. Use extinguishing media suitable for surrounding conditions. Cool fire-exposed cylinders until flames are extinguished. Damaged cylinders should be handled only by specialists.
Hazardous Combustion Products: Explosion Data:	None
Sensitivity to Mechanical Impact:	Not sensitive
Sensitivity to Static Discharge:	Not sensitive
Unusual fire/explosion hazards: Protective Equipment and	Cylinders could rupture under heat of fire.
Precautions for Firefighters:	As in any fire, wear self-contained breathing apparatus pressure-demand, MSHA/NIOSH (approved or equivalent) and full protective gear.

Section 6. ACCIDENTAL RELEASE MEASURES

Personal Precautions:

Evacuate personnel to safe areas. Ensure adequate ventilation, especially in confined areas. Monitor oxygen level.

Page 3 of 10 Pages Argon SDS Part Number 26929

Personal Protective Equipment:	Wear self-contained breathing apparatus when entering area unless atmosphere is proved safe.
Emergency Procedures:	Handle in accordance with good health and safety practices.
Methods for Containment:	Stop the flow of gas or remove cylinder to outdoor location if this can be done without risk. If leak is in container or container valve, contact the appropriate emergency telephone number in Section 1 or call your closest supplier location.
Methods for Clean Up: Other:	Return cylinder to authorized distributor. None

Section 7. HANDLING AND STORAGE

Personal Precautions:

Conditions for Safe Storage:

Only experienced and properly instructed persons should handle gases under pressure. If under pressure - Protect from sunlight and store in a cool, well-ventilated place. Always store and handle compressed gas cylinders in accordance with Compressed Gas Association, Pamphlet CGA-P1, Safe Handling of Compressed Gases in Containers. None

Incompatible Products:

Section 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Chemical Name	OSHA PEL	ACGIH TLV	DFG MAK *	EU BLV
Argon	NR	NR	NR	NR

*German regulatory limits; NR = Not Regulated.

Engineering Controls:

Local exhaust ventilation to prevent accumulation of high concentrations and maintain air-oxygen levels at or above 19.5%. Oxygen detectors should be used when asphyxiating gases may be released. Systems under pressure should be regularly checked for leakages.

Personal Protective Equipment – PPE Code E:





Eye/Face Protection: Skin and Body Protection: Respiratory Protection:





Tightly fitting safety goggles or face shield Wear protective gloves, safety shoes. If oxygen levels are unknown or are below 19.5%, use positive-pressure, supplied air respirator with escape cylinder. Respiratory protection must be provided in accordance with current local regulations. Good personal hygiene practices are essential, such as avoiding food, tobacco products, or other hand-tomouth contact when handling. Do not allow in eyes, on skin, or on clothing.

Hygiene Measures:

Section 9. PHYSICAL AND CHEMICAL PROPERTIES

Appearance: Molecular Weight: Odor: Odor Threshold: Decomposition Temperature ^oC: Freezing Point ^oC: Initial Boiling Point ^oC: Physical State: pH: Flash Point ^oC: Autoignition Temperature ^oC: Boiling Point/Range ^oC: Melting Point/Range ^oC: Flammability/Explosion Limits in Air ^oC: **Explosive Properties: Oxidizing Properties:** Volatile Component (%vol) **Evaporation Rate:** Vapor Density:

Colorless gas 39.95 Odorless None No information available -189.4-185.7 aat 760 mmHg Gas No information available None None -185.7-189.2Upper – None; Lower-None None None No information available No information available 1.38 at 21 C

Page 5 of 10 Pages Argon SDS Part Number 26929 Vapor Pressure: Specific gravity: Solubility: Partition Coefficient: Viscosity (absolute; 10⁻⁵ Pa s): 8.82E+007 at 25 C 1.38 at 21 C 0.058 at 20 C in water 1.28E-016 (Mackay model) gas coefficient 2.1 at 2.23 C

Section 10. STABILITY AND REACTIVITY

Stability: Incompatibles: Conditions to Avoid: Hazardous Decomposition Products: Possibility of Hazardous Reactions: Hazardous Polymerization Stable None High temperatures (>125^oF); poorly ventilated areas. None None Does not occur

Section 11. TOXICOLOGICAL INFORMATION

Likely Routes of Exposure: Symptoms: Immediate: Inhalation:

> Eyes: Skin:

Delayed:

Acute Toxicity:

Inhalation, skin and eye contact.

Increased respiration, headache, mild narcotic effects, increased blood pressure and pulse rate, unconsciousness, death. Contact with liquid/gas may cause burns/frostbite. Contact with liquid/gas may cause burns/frostbite. None Asphyxiate.Chronic Toxicity: None known. None known

Acute Toxicity Values - Health

Short-term Exposure: Long-term Exposure:

Chemical Name	LD50		LC50 (Inhalation)
	Oral	Dermal	
Argon	NA	NA	>82,000 ppm/4hr (rat)

Reproductive Toxicity:

Target Organs and Effects (TOST):

This product's ingredients are not known to have reproductive or teratogenic effects. This product's ingredients are not known to have reproductive or teratogenic effects.

Page 6 of 10 Pages Argon SDS Part Number 26929

Other Toxicity Categories

Chemical Name	Germ Cell Mutagenicity	Carcino- genicity	Repro- ductive	TOST Single Exp	TOST Repeated Exp	Aspiration
Argon	None	None	None	None	None	None

Section 12. ECOLOGICAL INFORMATION

Ecotoxicity:	No negative effects known
Persistence/Degradability:	No negative effects known,
Bioaccummulation: Mobility in soil:	No negative effects known. No negative effects known.
Other Adverse Ecological Effects:	No other known effects at this time

Aquatic Toxicity Values – Environment – None Known

Chemical Name	Acute (LC50)	Chronic (LC50)
Argon	N/A	N/A

Section 13. DISPOSAL CONSIDERATIONS

Safe Handling	Use appropriate PPE when handling (see Section 8). Only experienced and properly instructed persons should handle gases under pressure.
Waste Disposal Considerations	Dispose in accordance with federal, state, and local regulations. Typically containers are returned to an authorized distributor for disposal.
Contaminated Packaging	Dispose in accordance with federal, state, and local regulations.

NOTES:

This product is not a RCRA characteristically hazardous or listed hazardous waste. Dispose of according to state or local laws, which may be more restrictive than federal laws or regulations. Used product may be altered or contaminated, creating different disposal considerations.

Page 7 of 10 Pages <u>Argon</u> <u>SDS Part Number 26929</u>

Section 14. TRANSPORT INFORMATION

	DOT	TDG	Mexico	IMDG	ΙΑΤΑ
UN number	UN1006	UN1006	UN1006	UN1006	UN1006
UN proper shipping name	ARGON, COMPRESSED	ARGON, COMPRESSED	ARGON, COMPRESSED	ARGON, COMPRESSED	ARGON, COMPRESSED
Transport hazard class(es)	2.2	2.2	2.2	2.2	2.2
Packing group	-	-	-	-	-
Environmental hazards	No.	No.	No.	No.	No.

"Refer to CFR 49 (or authority having jurisdiction) to determine the information required for shipment of the product."

Special Precautions for Shipping:

If shipped in a stored pressure-type fire extinguisher, and pressurized with a non-flammable, nontoxic inert expellant gas, the fire extinguisher is considered a hazardous material by the US Department of Transportation and Transport Canada. The proper shipping name shall be FIRE EXTINGUISHER and the UN designation is UN 1044. The DOT hazard class/division is LIMITED QUANTITY when pressurized to less than 241 psig and when shipped via highway or rail. UN Class 2.2. Non-Flammable Gas, when shipping via air. Packing Group – N/A

Section 15. REGULATORY INFORMATION

International Inventory Status:	All ingredients are on the following inventories			
Country(ies)	Agency	Status		
United States of America	TSCA	Yes		
Canada	DSL	Yes		
Europe	EINECS/ELINCS	Yes		
Australia	AICS	Yes		
Japan	MITI	Yes		
South Korea	KECL	Yes		
Mexico	INSQ	Yes		

REACH Title VII Restrictions:

No information available

Chemical Name	Dangerous Substances	Organic Solvents	Harmful Substances Whose Names Are to be Indicated on Label	Pollution Release and Transfer Registry (Class II)	Pollution Release and Transfer Registry (Class I)	Poison and Deleterious Substances Control Law
Argon	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable

Page 8 of 10 Pages <u>Argon</u> <u>SDS Part Number 26929</u>

Component	ISHA – Harmful Substances Prohibited for Manufacturing, Importing, Transferring, or Supplying	ISHA – Harmful Substances Requiring Permission	Toxic Chemical Classification Listing (TCCL) – Toxic Chemicals	Toxic Release Inventory (TRI) – Group I	Toxic Release Inventory (TRI) – Group II
Argon 7440-37-1	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable

European Risk and Safety phrases:

EU Classification:

R Phrases:	None
S Phrases:	None

U.S. Federal Regulatory Information:

SARA 313:

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA) - This product does not contain and chemicals which are subject to the reporting requirements of the Act and Title 40 of the Code of Federal Regulations, Part 372. None of the chemicals in this product are under SARA reporting requirements or have SARA threshold planning quantities (TPQs) or CERCLA reportable quantities (RQs), or are regulated under TSCA 8(d).

SARA 311/312 Hazard Categories:

Acute Health Hazard	No
Chronic Health Hazard	No
Fire Hazard	No
Sudden Release of Pressure Hazard-*	Yes
Reactive Hazard	No

* - Only applicable if material is in a pressurized extinguisher.

Clean Water/Clean Air Acts:

This product does not contain any substances regulated as pollutants pursuant to the Clean Water Act (40 CFR 122.21 and 40 CFR 122.42) or Clean Air Act, Section 112 Hazardous Air Pollutants (HAPs) (see 40 CFR 61) and Section 112 of the Clean Air Act Amendments of 1990.

U.S. State Regulatory Information:

Chemicals in this product are covered under specific State regulations, as denoted below:

Alaska - Designated Toxic and Hazardous Substances: None **California** – Permissible Exposure Limits for Chemical Contaminants: None

> Page 9 of 10 Pages Argon SDS Part Number 26929

Florida – Substance List: None Illinois – Toxic Substance List: None Kansas – Section 302/303 List: None Massachusetts – Substance List: None Minnesota – List of Hazardous Substances: None Missouri – Employer Information/Toxic Substance List: None New Jersey – Right to Know Hazardous Substance List: None North Dakota – List of Hazardous Chemicals, Reportable Quantities: None Pennsylvania – Hazardous Substance List: None Rhode Island – Hazardous Substance List: None Texas – Hazardous Substance List: None West Virginia – Hazardous Substance List: None Wisconsin – Toxic and Hazardous Substances: None

California Proposition 65: No component is listed on the California Proposition 65 list.

Other:

Mexico – Grade Canada – WHMIS Hazard Class No component listed No component listed

Section 16. OTHER INFORMATION

This SDS conforms to requirements under U.S., U.K., Canadian, Australian, and EU regulations or standards, and conforms to the proposed 2003 ANSI Z400.1 format. No modifications of this SDS are authorized by AMEREX Corporation. Questions or comments should be directed to AMEREX Corporation (See Section 1).

Issuing Date Revision Date Revision Notes 17-June-2012 9-February 2021; Revision D None

The information herein is given in good faith but no warranty, expressed or implied, is made. Updated by Jordan Harbison.

Page 10 of 10 Pages Argon SDS Part Number 26929